

POSSIBLE INTERFERENCE
between support tooth and screw. To solve this problem it is necessary to file the support's tooth.