


1



M3 x 15 mm


M3 x 10 mm

| CADRO Glass display case


Glass door lock.

Assembly instructions.


2




10



3








Contents.




- 1x Lock with premounted screws
- 1x Bushing for latch
- 1x Ball catch
- 2x Key

4






9 Drilling dimensions for profiles and glass door.



x $x_{\min} = 50$ mm

a Hole for latch = $x + 14$ mm

b Hole for ball catch = $x - 4,5$ mm



x $x_{\min} = 50$ mm

a Hole for latch = $x - 6$ mm

b Hole for ball catch = $x + 12,5$ mm